
- LUMINAIRE HAS BEEN PROPERLY PACKED SO THAT NO PARTS SHOULD HAVE BEEN DAMAGED DURING TRANSIT. INSPECT TO


ELECTRICIAN. - LUMINAIRE MUST BE INSTALLED BY A CERTIFIED

FAILURE TO FOLLOW INSTALLATION INSTRUCTIONS OR MODIFICATIONS MADE TO LUMINAIRE WILL VOID THE MANUFACTURER'S WARRANTY.

USE SILICONE WHEN MOUNTING TO SURFACE TO ENSURE A WATER TIGHT SEAL



OCTAGONAL J-BOX RATED FOR 30LBS (HARDWARE PROVIDED BY OTHERS) STEP 1: INSTALL CEILING CANOPY TO STANDARD 4"



STEP 2: INSTALL HOUSING CANOPY TO CEILING CANOPY WITH HARDWARE

PROVIDED.

P.A.C.E. ILLUMINAITION NO MAINTENANCE OR INSTALLATION OF GASKET REQUIRED LENS FRAME GASKET APPLIED BY WARNING:

- RISK OF ELECTRIC SHOCK: TURN POWER OFF BEFORE SERVICING.

LISTED FOR WET LOCATION

THIS PRODUCT MUST BE INSTALLED IN ACCORDANCE WITH THE APPLICABLE INSTALLATION CODE BY A PERSON FAMILIAR WITH THE CONSTRUCTION AND OPERATION OF THE PRODUCT AND THE HAZARDS INVOLVED

CE PRODUIT DOIT ÉTRE INSTALLÉ
SELON LE CODE D'INSTALLATION
PERTINENT, PAR UNE PERSONNE
QUI CONNAÎT BIEN LE PRODUIT ET
SON FONCTIONNEMENT AINSI QUE LES RISQUES INHÉRENTS

ESTE PRODUCTOR DEBE SER
INSTALADO SEGUN EL CODIGO DE
INSTALACION APLICABLE POR UNA
PERSONA QUE CONOZCA LA
CONSTUSSION Y EL
FUNCIONAMIENTO DEL PRODUCTO Y
LOS RIESGOS QUE SUPONE

These instructions do not purport to cover all details or variations in equipment nor to provide for every possible contingency to be met in

MAINTENANCE	DESCRIPTION	CAKALBASHLEGAD!	connectionwith	
RIEASE FOLLOW I.E.S. SPECS FOR	INSTALLATION INSTRUCTIONS	9xeredsufficiently for the purchaser's purposes the matter should be referred to PACE Illumination UNITS INCHES SIZE	connectionwith installation, operation or maintenance. Should further information be desired or should particular problems arise	
SCALE N/A	SHEET 10F1	to PACE Illuminatio	n be desired or sho	
SCALE N/A APRV BY PARM DATE	SHEET 10F1 DRW BY PARM DATE	"UNITS INCHES	ula particular probler	
DATE	DATE	SIZE	ms arise	
06JUL24	06JUL24	LETTER	which are not	
	Craw Verlag (Sterr-Verz_Leps Ma			